



# Texas Department of Licensing and Regulation

## Architectural Barriers Project Details Page

Project #: TABS2021015091

Registration Date: 5/6/2021

<https://www.tdlr.texas.gov/TABS/Projects/TABS2021015091>

### PROJECT

**Project Name:** Ball Storage  
**Project Number:** TABS2021015091  
**Facility Name:** Ball Storage  
**Location Address:** 2115 Winnie  
Galveston, TX 77550  
**Location County:** Galveston  
**Start Date:** 9/1/2021  
**Completion Date:** 3/1/2022  
**Estimated Cost:** \$4,000,000  
**Type of Work:** Renovation/Alteration  
**Type of Funds:** This project is privately funded, on private land for private use.  
**Scope of Work:** Renovate existing to self storage  
**Square Footage:** 71,502 ft<sup>2</sup>  
**Are the private funds provided by the tenant?** Yes  
**Current Status:** Review Complete

### PERSON FILING FORM

**Contact Name:** Shannon Quijano

### RAS

Not Assigned

### OWNER

**Owner Name:** Cantour Group  
**Owner Address:** 520 Newport Center Drive  
Newport Beach, California 92660  
**Owner Phone:** (409) 762-8000  
**Contact Name:**

### TENANT

Not Assigned

### DESIGN FIRM

Not Assigned

Registered accessibility specialists (RAS) set and collect the fees for their services. Contact the RAS directly if you have questions about their performing plan review or inspection services.

In accordance with 16 TEX. ADMIN. CODE §68.52, the owner of a building or facility must obtain an inspection from a RAS no later than the first anniversary of the completion of construction. A request for inspection must be made by submitting a written request for inspection to the RAS no later than 30 calendar days after the completion of construction.